

0010

Outgoing

C0070042

OK

From: Karl Houskeeper
To: rnetz@emerytelcom.net
CC: Angela Nance; Daron Haddock; Suzanne Steab
Date: 8/4/2009 1:57 PM
Subject: July 2009 Inspection Reports
Attachments: SPWF July 2009.pdf; SCA July 2009.pdf

Rusty,

Attached is the July 2009 inspection reports for SPWF and SCA.

Thanks,
Karl



State of Utah
Department of
Natural Resources

MICHAEL R. STYLER
Executive Director

Division of
Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:

Company	Rusty Netz	Environmental Coordinator
OGM	Karl Houskeeper	Environmental Scientist III

Inspection Report

Permit Number:	C0070042
Inspection Type:	PARTIAL
Inspection Date:	Thursday, July 16, 2009
Start Date/Time:	7/16/2009 8:30:00 AM
End Date/Time:	7/16/2009 10:30:00 AM
Last Inspection:	Thursday, June 18, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 85 Deg. F.

InspectionID Report Number: 2066

Accepted by: jhelfric
8/4/2009

Permitee: **SUNNYSIDE COGENERATION ASSOCIATES**

Operator: **SUNNYSIDE COGENERATION ASSOCIATES**

Site: **STAR POINT REFUSE**

Address: **ONE POWER PLANT RD, PO BOX 159 SUNNYSIDE UT 84539**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

Current Acreages

152.93	Total Permitted
152.93	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- ☐ Federal
☐ State
☐ County
☒ Fee
☐ Other

Types of Operations

- ☐ Underground
☐ Surface
☐ Loadout
☐ Processing
☒ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl R. Houskeeper

Date

Thursday, July 16, 2009

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0070042
 Inspection Type: PARTIAL
 Inspection Date: Thursday, July 16, 2009

Inspection Continuation Sheet

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Permit Number: C0070042
Inspection Type: PARTIAL
Inspection Date: Thursday, July 16, 2009

Inspection Continuation Sheet

Page 3 of 3

2. Signs and Markers

The mine ID signs are located at the contact points of the public road to the permit area and contains all of the appropriate information. All other signs and markers observed during the inspection were in compliance with the approved MRP.

4.a Hydrologic Balance: Diversions

A erosional cut on the outslope of the refuse pile following the buried culvert that directs run off from the top of the refuse pile needs to be dressed and compacted.

4.c Hydrologic Balance: Other Sediment Control Measures

Several sediment retention basins are at capacity abd need to be cleaned.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile is being actively mined in lifts. The pile is stable with no visible hazards.